


1/18

FIG.1




2/18

FIG.2


DATA No. T	Y 3LL, 3HL-LH-HH, 2HL-LH-HH, 1HL-LH-HH Cb 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH Cr 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH	DATA No. T	Y 3LL, 3HL-LH-HH, 2HL-LH-HH, 1HL-LH-HH Cb 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH Cr 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH
T=0	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 1 0, 0 0 0, 0 0 0, 0 0 0	T=399	1, 1 1 3, 4 4 6, 101017 9, 101013, 141418, 202027 8, 9 911, 121216, 181823
T=1	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 2 0, 0 0 0, 0 0 0, 0 0 0	T=400	1, 1 1 3, 4 4 6, 101017 9, 101013, 141418, 202027 8, 9 911, 121216, 181823
T=2	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 3 0, 0 0 0, 0 0 0, 0 0 0	⋮	⋮
⋮	⋮	T=499	
T=99	0, 0 0 0, 0 0 0, 0 0 6 0, 0 0 3, 4 4 8, 101017 0, 0 0 1, 2 2 6, 7 713	T=500	
T=100	0, 0 0 0, 0 0 0, 0 0 7 0, 0 0 3, 4 4 8, 101017 0, 0 0 1, 2 2 6, 7 713	⋮	⋮
⋮	⋮	T=1000	
T=199	0, 0 0 0, 0 0 0, 5 511 3, 4 4 7, 8 813, 151521 2, 3 3 6, 7 710, 121217	⋮	⋮
T=200	0, 0 0 0, 0 0 0, 5 511 3, 4 4 7, 8 813, 151522 2, 3 3 6, 7 710, 121217	T=1500	
⋮	⋮	⋮	⋮
T=299	0, 0 0 0, 1 1 4, 8 814 6, 7 710, 111216, 181825 6, 6 6 9, 101013, 151520	⋮	⋮
T=300	0, 0 0 0, 1 1 4, 8 814 6, 7 710, 121216, 181825 6, 6 6 9, 101013, 151520	⋮	⋮
⋮	⋮	⋮	⋮

FIG.3




4/18

FIG.4



5/18

FIG.5



6/18

FIG.6






FIG.7




7/18

FIG.8




8/18

FIG.9




9/18

FIG. 10



10/18

FIG. 11



11/18

FIG.12





FIG. 13



13/18

FIG.14




FIG.15




FIG. 16





FIG. 17



17/18

FIG.18




FIG. 19

